ENVIRONMENTAL CONSULTATION & TRAINING

CLOSURE REPORT FOR THE ABANDONMENT AND REMOVAL OF AN UNDERGROUND FUEL STORAGE TANK

At

The Boeing Company 19503 South Normandie Avenue Los Angeles, CA. 90502

Prepared For

Perry Manes, Inc. 1101 East Spring Street Signal Hill, CA. 90807 Attn: Mr. Perry Manes

Submitted To

Los Angeles City Fire Department Underground Tank Enforcement Unit Bureau of Fire Prevention 200 North Main Street, Rm. 930, CHE Los Angeles, CA. 90012 Attn: Mr. Dean J. Stivason, Inspector

January, 21, 1999

Prepared By:

Thomas Twillie, Project Mgr./

Chemist/REA/REHS

Reviewed/Supervised By:

Efren V. Ancheta, P.E.

Registered Engineer, 41704



14616 LAKEWOOD BLVD., BELLFLOWER, CA. 90706 (310) 630-0444

Table of Contents

- 1.) Introduction
- 2.) Underground Tank Removal and Disposal
 - 2.1 Tank Cleaning
 - 2.2 Degassing of Tank
- 3.) Sampling and Analysis
- 4.) Geology and Hydrogeology
- 5.) Results
- 6.) Backfill and Compaction
- 7.) Conclusion and Recommendation
- 8.) Appendices

Figures

Figure 1 - Site Map Figure 2 - Plot Plan

Appendix

Appendix A - Laboratory Test Results and Chain of Custody

Appendix B - Marine Chemist Certificate

Appendix C - Soil Compaction Report

Appendix D - Uniform Hazardous Waste Manifest

Appendix E - Tank Degassing Certificate

Appendix F - Tanks Destruction Certificates

Appendix G - Permit

→ Appendix H - Soil Compaction Report

On December 18, 1998, Perry Maness, Inc. and Subcontractor Lopez General Engineering Contractors, Inc. was retained by The Boeing Company for the removal and disposal of a twelve thousand gallons unleaded gasoline underground fuel storage tank at their Torrance, California facility. The facility is located at 19503 So. Normandie Avenue, Torrance, California.

The facility operations have been reduced or relocated over the past several years. A significant portion of the property has been redeveloped and converted to an office and commercial occupants. The pump dispenser and island was left in place for the existing tank in operation. The unleaded gasoline underground storage tank was removed via the Los Angeles City Fire Department permit # 7572. The underground storage tank is located at the service garage, Building #20.

2.0 Underground Tank Preparation

The underground storage tank was isolated by the disconnection of it's electrical service and piping. All residual gasoline was removed from the tank and pipings were pressure wash with the rinseate and pumped onto a vacuum tanker truck, registered to haul hazardous waste to a permitted TSD facility for recycling via an uniform hazardous waste manifest. The concrete pad was removed and the tank was excavated to exposed the top. The tank was pressure washed to remove all residual product with emission being scrubbed with a SCAQMD permitted degassing unit. The excavated soil was stockpiled on plastic and a temporary fence was installed around the tank excavation for safety purposes as required by the City of Los Angeles Fire Department.

3.0 Underground Tank Removal

The underground tank was removed via the City of Los Angeles Fire Department permit # 7572 and was witness by Inspector, Mr. Dean J. Stivason. The twelve thousand gallons unleaded gasoline steel tank was removed from the excavation with a crane. The underground tank was loaded onto a flatbed trailer. The tank was transported to a metal recycler for disposal via a Bill of Laden and Marine Chemist Certificate. A letter of tank destruction is included in the appendix.

4.0 Sampling and Analysis

A total of three (3) vadose soil samples were collected during the removal of the underground tank at the subject site. A soil sample was collected at each end of the tank invert of the bottom of the excavation three feet (3ft) deep. A backhoe was utilized to collect the samples from the bottom of the excavation. Then, a hand auger and hammer attached sampler lined with 1.5 inch brass liners was utilized to retrieve sample from the bucket of the backhoe. The hammer and attached sampler containing

the brass liner was used to retrieve the undisturbed sample. The sample was removed from the sampler in the liner and ends were covered with Teflon sheeting, capped, sealed, labeled, and place on ice. The samples were transported to a state certified analytical laboratory for analysis via a chain of custody form.

The soil samples were tested for Total Petroleum Hydrocarbons-gasoline (TPH-Gas) by CAL-EPA-DTSC Test Method 8015 (gasoline), Volatile Aromatic Hydro-Carbons (BTXE+MTBE) by EPA Test Method 8020, and Total Lead (TTLC) by EPA Test Method 7420. The appropriate detection limits were utilized in accordance to CAL-EPA and EPA Test Protocols.

5.0 Geology and Hydrogeology

The facility is located in the southern portion of the West Coast Hydrologic Subarea of the Los Angeles Basin. More specifically, the project site lies in the Torrance Plain, which borders the Newport-Inglewood belt of hills from Ballona Gap southwest of Dominguez Gap. Water bearing sediments and marine and non-marine origin underlie the plain. Sediments of the Upper Pleistocene Lakewood Formation underlie the site. This geologic unit is approximately 150 feet below the project site. Beneath the Lakewood Formation lies the lower Pleistocene San Pedro Formation, which has a thickness of approximately 1200 feet in this area.

The Pleistocene San Pedro Formation is divided into various stratigraphic units with those units capable of storing water named as aquifers. These aquifers from top to bottom include: The Hollydale, Jefferson, Lynwood, Silverado, and Sunnyside Aquifers. The Silverado and Sunnyside Aquifers underlies the site. The Silverado Aquifer is composed of both continental and marine deposits. The continental deposits include coarse to fine sand and gravels interbedded with silts and clays while the marine deposits include sand, gravel, silt, and clay.

The local hydrogeology at the site is predominantly silts and clays to depths of 25 to 50 feet below surface grade. Below 50 feet the semi-perched aquifer consist of sedimentary deposits typical of flood-plain alluvial deposits that includes sand-filled channels with interbeds and lateral gradation to fine sand material. The upper portion of the semi-perched aquifer appears to consist of sands and silty sands with occasional discontinuous interbeds of silt and clay. Soils underlying approximately the 110 feet depth are composed of thinner beds of sand, silty sand, and clays.

The latest groundwater data within the vicinity of the subject site was obtained from Los Angeles County Flood Control District-Hydrology Section. Groundwater Well #794-A, located at 190th Street and Antsf RR, just west of the site, Torrance, California. The depth to groundwater from surface grade is 102.7 feet with a ground elevation of 51 feet. The last date of measurement was November 6, 1997.

A total of three (3) soil boring samples were collected at the subject site during the removal of the underground unleaded gasoline storage tank. The soil sample test results are as follows:

Table I
UST CLOSURE SAMPLE TEST RESULTS

Sample #	Contaminant	Matrix		ntration (g/kg)
TK 1A-3-98	Total Petroleum Hydrocarbons-gas	Soil	South end of tank 3 feet deep	N.D.
TK 1B-3-98	n	"	North end of tank 3 feet deep	<i>N.D</i> .
SP-1-3-98	"	**	Spoil pile	<i>N.D.</i>
TK 1A-3-98	MTBE Benzene	Soil "	South end of tank	N.D. N.D
	Toluene	**	n	N.D.
	E. Benzene	"	"	N.D. N.D.
	Xylenes	"	"	N.D. N.D
	Lead	,	,	4.2 Mg/Kg.
TK 1B-3-98	MTBE	"	North end of tank	<i>N.D</i> .
	Benzene	"	"	<i>N.D</i> .
!	Toluene	n	"	<i>N.D.</i>
	E. Benzene	"	"	<i>N.D</i> .
	Xylenes	**	"	<i>N.D.</i>
	Lead	"	11	5.1 Mg/Kg
SP-1-3-98	MTBE	"	Spoil pile	<i>N.D</i> .
	Benzene	"	- <i>"</i>	<i>N.D.</i>
	Toluene	"	"	<i>N.D</i> .
	E. benzene	**	"	<i>N.D.</i>
	Xylenes	. "	"	<i>N.D.</i>
	Lead		" .	3.6 Mg/Kg

N.D. = Not Detected: MTBE= Methyl-tert-butyl Ether


The test results of the soil samples were all non-detect for the presence of total petroleum hydrocarbons (TPHs-gas) and Volatile Aromatic Hydrocarbons (BTEX & MTBE). Therefore, the stockpile excavated soil maybe used for backfill and no further action at the site is required.

8.0 Recommendation and Conclusion

The removal and abandonment of the underground-unleaded gasoline storage tank has been completed. The underground tank was excavated, cleaned, removed and disposed off in according to the City of Los Angeles Fire Department UST regulations. The underground tank rinseate was transported and disposed via a uniform hazardous waste manifest at a permitted TSD facility. The tank was transported to a metal recycler for disposal via a bill of laden and a marine chemist certificate. The closure soil samples test results were all non-detect and below regulatory agencies action limits requiring no further action. It is recommended that the tank excavation be backfill with the excavated stock piled and clean imported material. The underground tank removal and abandonment project is considered to be complete requiring no further action at the subject site.

Appendix

<u>Figure 1</u> Site Map



CS FACILITY




Figure -2


<u>Plot Plan</u>

Figure 1: Site Plan


Boeing Torrance 19503 South Normandie Torrance, California

Building 20

Dispenser Island



DOITNTTR



T & T Environmental Services

14616 Lakewood Boulevard, Bellflower CA 90706

Appendix A

Laboratory Test Results and Chain of Custody



Testing Laboratories

P.O. Box 5387 • Fullerton, CA 9283:

(714) 449-9937 • FAX (714) 449-968

JONES ENVIRONMENTAL LABORATORY RESULTS

Client:

Lopez

2633 E. 28th St., #624

Report Date: JEL Ref. No.: 12/02/98

Signal Hill, CA 90806

Client Ref. No.:

B-2240

Attn:

Thomas Twillie

Date Sampled:

11/24/98

Date Received:

11/24/98

Project:

Client Address:

Boeing

Date Analyzed:

11/24/98

Project Address:

Long Beach, CA

Physical State:

Soil

Modified 8015 Diesel (Simulated Distillation Extended Range)

Sample ID Concentration (mg/Kg)

Carbon Chain Range	TK-2W-	TK-3W-	<u>TK-4W-</u>	TK-5W-
0.00	LBD-3-98	LBD-3-98	LBD-3-98	LBD-3-98
C6-C7	ND	ND	ND	ND
C8-C9	ND	ND	39	ND
C10-C11	ND	ND	270	ND
C12-C13	ND	ND	360	ND
C14-C15	ND	ND	180	ND
C16-C17	ND	ND	45	ND
C18-C19	ND	ND	12	ND
C20-C23	ND	ND	ND	ND
C24-C27	ND	ND	ND	ND
C28-C31	ND	ND	ND	ND
C32-C35	ND	ND	ND	ND
C36-C39	ND	ND	ND	ND
C40-C43	ND	ND	ND	ND
C44+	ND .	ND	·ND	ND
Total	ND	ND	910	ND
Reporting Limits	10	10	10	10
Surrogate Recovery %	116	98	95	96



Testing Laboratories JONES ENVIRONMENTAL

P.O. Box 5387 • Fullerton, CA 92838

(714) 449-9937 • FAX (714) 449-9685

LABORATORY RESULTS

Client: Client Address: Lopez

2633 E. 28th St., #624 Signal Hill, CA 90806

Report Date: JEL Ref. No.: 12/02/98

Client Ref. No.:

B-2240

Attn:

Thomas Twillie

Date Sampled:

11/24/98

Date Received:

11/24/98

Project: **Project Address:**

Boeing

Date Analyzed:

11/24/98

Long Beach, CA

Physical State:

Soil

Modified 8015 Diesel (Simulated Distillation Extended Range)

Sample ID Concentration (mg/Kg)

<u>Carbon Chain Range</u> <u>TK-1E-</u> <u>LBD-3-98</u>	<u>TK-2E-</u> <u>LBD-3-98</u>	<u>TK-3E-</u> LBD-3-98	TK-4E-	TK-5E-	TK-1W-
			LBD-3-98	LBD-3-98	LBD-3-98
	ND	ND	40	ND	ND
C8-C9 ND	ND	3.6	620	ND	27
C10-C11 77	ND	11	1600	ND	190
C12-C13 330	ND	29	1700	ND	370
C14-C15 200	ND	25	880	ND	240
C16-C17 58	ND	14	140	ND	50
C18-C19 ND	ND	9.0	12	ND	11
C20-C23 ND	ND	7.2	4.3	ND	ND
C24-C27 ND	ND	ND	ND	ND	ND
C28-C31 ND	ND '	ND	ND	ND	ND -
C32-C35 ND	ND.	ND	ND	ND	ND
C36-C39 ND	ND ·	ND	ND	ND	ND
C40-C43 ND	ND	ND	ND	ND	ND
C44+ ND	ND	ND	ND	ND	ND
Total 670	ND	99	5000	ND	890
Reporting Limits 10	10	~ 10	10	10	10
Surrogate Recovery % 113	76	83	85	119	87



Testing Laboratories

P.O. Box 5387 • Fullerton, CA 92838

(714) 449-9937 • FAX (714) 449-9685

JONES ENVIRONMENTAL

LABORATORY RESULTS

Client: Client Address: Lopez

2633 E. 28th St., #624

Report Date: JEL Ref. No.: 12/02/98

Signal Hill, CA 90806

B-2240

Client Ref. No.:

Attn:

Thomas Twillie

Date Sampled:

11/24/98

Project:

Boeing

Date Received:

11/24/98

Date Analyzed:

11/24/98

Physical State:

Soil

Project Address: Long Beach, CA

Modified 8015 Diesel (Simulated Distillation Extended Range)

Sample ID Concentration (mg/Kg)

Carbon Chain Range	<u>SP-1-LBD-</u> <u>98</u>	<u>SP-2-LBD-</u> <u>98</u>	<u>SP-3-LBD-</u> <u>98</u>	SP-4-LBD-	SP-5-LBD-	SP-6-LBD-
C6-C7	ND	ND	ND	<u>98</u> ND	<u>98</u> ND	<u>98</u> ND
C8-C9	ND	ND	ND	ND	ND	ND
C10-C11	27	ND	ND	ND	ND	ND
C12-C13	73	ND	ND	ND	ND	ND
C14-C15	68	ND	ND	ND	16	ND
C16-C17	6.7	ND	ND	ND	ND	ND
C18-C19	9.2	ND	ND	ND	ND	ND
C20-C23	2.5	ND	ND	ND	ND	ND
C24-C27	ND	ND	ND	ND	ND	ND
C28-C31	ND	ND	ND	ND	ND	ND
C32-C35	ND	ND	ND	ND	ND	ND
C36-C39	ND	ND	ND	ND	ND	ND
C40-C43	ND	ND	ND	ND	ND	ND
C44+	ND	ND	ND	ND	ND	ND
Total	190	ND	ND	ND	16	ND
Reporting Limits	10	10	10	10	10	10
Surrogate Recovery %	117	83	109	81	103	98



Testing Laboratories

JONES ENVIRONMENTAL

P.O. Box 5387 • Fullerton, CA 92838

(714) 449-9937 • FAX (714) 449-9685

LABORATORY REPORT

Client: Client Address: Lopez

2633 E. 28th St., #624

Report Date: JEL Ref. No.: 12/02/98

Signal Hill, CA 90806

Client Ref. No.:

B-2240

Attn:

Thomas Twillie

Date Sampled:

11/24/98

Project:

Boeing

Date Received: Date Analyzed:

11/24/98 11/24/98

Project Address:

Long Beach, CA

Physical State:

Soil

ANALYSES REQUESTED

1. Mod 8015 Diesel - Simulated Distillation Extended Range

Approval:

Steve Jones, Ph.D. Laboratory Manager



Testing Laboratories

P.O. Box 5387 • Fullerton, CA 92838

JONES ENVIRONMENTAL

(714) 449-9937 • FAX (714) 449-9685

QUALITY CONTROL INFORMATION

Client:

Lopez

2633 E. 28th St., #624

Report Date: JEL Ref. No.: 12/02/98

Signal Hill, CA 90806

Client Ref. No.:

B-2240

Attn:

Thomas Twillie

Date Sampled:

11/24/98

Project:

Date Received:

11/24/98

Project Address:

Client Address:

Boeing Long Beach, CA Date Analyzed:

11/24/98

Physical State:

Soil

Modified 8015 Diesel (Simulated Distillation Extended Range)

Sample Spiked: SP-2-LBD-98

MS

MSD

Acceptability

Parameter

Recovery (%)

Recovery (%)

<u>RPD</u>

Range (%)

Diesel

96%

100%

3.8%

8.3%

65 - 125

Sample Spiked: SP-3-LBD-98

MS

MSD

Acceptability

65 - 125

Parameter

Recovery (%)

Recovery (%)

<u>RPD</u> Range (%)

Diesel

103%

95%

Method Blank = Not Detected

MS

= Matrix Spike

MSD

= Matrix Spike Duplicate

RPD

= Relative Percent Difference



Testing Laboratories

P.O. Box 5387 • Fullerton, CA 92838 (714) 449-9937 • FAX (714) 449-9685

JONES ENVIRONMENTAL

LABORATORY RESULTS

Client:

Client Address:

T & T Environmental Services

14616 Lakewood Blvd.

Bellflower, CA 90706

Report Date: JEL Ref. No.:

12/23/98 B-2263

Client Ref. No.:

Attn:

Thomas Twillie

Date Sampled:

12/18/98

Project:

_ .

Date Received: Date Analyzed:

12/22/98

Project Address:

Boeing Torrance, CA

Date Analyze

12/22/98

Physical State:

Soil

EPA 8020 - Volatile Aromatic Hydrocarbons

		Concentra	tion (mg/Kg)	Reporting				
Sample ID	MTBE	<u>Benzene</u>	Toluene	Ethylbenzene	Xylenes	Limits (mg/Kg)	Surrogate Recovery %	
SP-1-3-98	ND	ND	ND	ND	ND	0.005	85	
TK1A-3-98	ND	ND	ND	ND	ND	0.005	. 98	
TK1B-3-98	ND	ND	ND	ND	ND	0.005	82	



Testing Laboratories

P.O. Box 5387 • Fullerton, CA 92838

(714) 449-9937 • FAX (714) 449-9685

JONES ENVIRONMENTAL

QUALITY CONTROL INFORMATION

Client: Client Address: T & T Environmental Services

14616 Lakewood Blvd.

Bellflower, CA 90706

Report Date:

12/23/98 JEL Ref. No.: B-2263

Client Ref. No.:

Attn:

Thomas Twillie

Date Sampled:

12/18/98

Project:

Boeing

Date Received: Date Analyzed: 12/22/98

Project Address:

Torrance, CA

Physical State:

12/22/98 Soil

EPA 8020 - Volatile Aromatic Hydrocarbons

Sample Spiked: TANK 4 (B2262)

<u>Parameter</u>	MS Recovery (%)	MSD Recovery (%)	RPD	Acceptability Range (%)
Toluene	107%	103%	3.6%	65 - 125
o-Xylene	103%	100%	2.6%	65 - 125

Method Blank = Not Detected

MS = Matrix Spike

= Matrix Spike Duplicate MSD

= Relative Percent Difference RPD



Testing Laboratories

P.O. Box 5387 • Fullerton, CA 92838

JONES ENVIRONMENTAL

(714) 449-9937 • FAX (714) 449-9685

LABORATORY RESULTS

Client: Client Address: T & T Environmental Services

14616 Lakewood Blvd.

Bellflower, CA 90706

Report Date: JEL Ref. No.: 12/23/98 B-2263

Client Ref. No.:

Attn:

Thomas Twillie

Date Sampled:

12/18/98

Project:

Boeing

Date Received:

12/22/98

Project Address:

Torrance, CA

Date Analyzed:

12/22/98

Physical State:

Soil

Modified EPA 8015 - Volatile Hydrocarbons (Gasoline)

Sample ID	Concentration (mg/Kg)	Surrogate Recovery %	Reporting Limits (mg/Kg)
SP-1-3-98	ND	9 8	1.0
TK1A-3-98	ND	105	1.0
TK1B-3-98	ND	115	1.0



Testing Laboratories

P.O. Box 5387 • Fullerton, CA 92838

(714) 449-9937 • FAX (714) 449-9685

JONES ENVIRONMENTAL QUALITY CONTROL INFORMATION

Client:

T & T Environmental Services

Report Date:

12/23/98

Client Address:

14616 Lakewood Blvd.

JEL Ref. No.:

B-2263

Bellflower, CA 90706

Client Ref. No.:

Attn:

Thomas Twillie

Date Sampled:

12/18/98

Project:

Date Received:

12/22/98

Project Address:

Boeing

Date Analyzed:

12/22/98

Torrance, CA

Physical State:

Soil

Modified EPA 8015 - Volatile Hydrocarbons (Gasoline)

Sample Spiked: TANK 4 (B-2262)

MS

MSD

Acceptability

Parameter

Recovery (%)

Recovery (%)

<u>RPD</u>

Range (%)

Gasoline

107%

104%

2.9%

65 - 125

Method Blank = Not Detected

MS

= Matrix Spike

MSD

= Matrix Spike Duplicate

RPD

= Relative Percent Difference



Testing Laboratories

JONES ENVIRONMENTAL

P.O. Box 5387 • Fullerton, CA 92838

(714) 449-9937 • FAX (714) 449-9685

LABORATORY REPORT

Client:

T & T Environmental Services

Report Date:

12/23/98

Client Address:

14616 Lakewood Blvd.

JEL Ref. No.:

B-2263

Bellflower, CA 90706

Client Ref. No.:

Attn:

Thomas Twillie

Date Sampled:

12/18/98

Project:

Boeing

Date Received:

12/22/98

Date Analyzed:

12/22/98

Project Address:

Torrance, CA

Physical State:

Soil

ANALYSES REQUESTED

1. EPA 8020 - Volatile Aromatic Hydrocarbons

2. Mod 8015 Gasoline - Volatile Hydrocarbons

Approval:

Steve Jones, Ph.D. Laboratory Manager

JUNES ENVIRONMENTAL TESTING LABORATORIES

P.O. BOX 5387 FULLERTON, CA 92635

> Tel: 714 449-9937 Fax: 714 449-9685

Chain-Of-Custody Record

alent .				12-12-	-98				,	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	/	8	Analy	rsis F	seques	ted ,	JEL Project #
reject Name	Torvano	 ب		12-18- Glient Preject i						3/-	3/2		/			/	/ B7263
Torran	So. Norm		Bre	Hush 7:	ats Attention 4-48 Hours 2-96 Hours	Laboratory		Se Maliix Soil (S)	0015 P. Sugar	(A)	10 / 10 / 10 / 10 / 10 / 10 / 10 / 10 /				//	Me	Container/Comments
Sample ID	•	Location		Date	Time	Laboratory Sample Number		7			7-{	-{	-{		/ {	1	/ Container/Comments
5p-1-3-98	5 pails	pile		12/18/98	1:10 PM	Bruz 1	5		-				-				
TRIA-3-9	8 Northerd	g TK	Bottom	u	1:4584	Burs	5	V	0								
TK1B-348	5 pails 8 Novthend 5 sythend	JTK	Botton		1:20 AM	B7167-3	<u>ک</u>	V	V	~		_	_	-		1	
							_		_						'		
			···········				-	_		ļ							
			نىي برسىيىنى بىيە دېدە يېسىدادىد		<u> </u>	ļ		-	-	<u> </u>							
				1	ļ	ļ <u> </u>	-	<u> </u>	_						İ	 	
				ļ			ļ	-	<u> </u>	ļ -					<u> </u>		
							_	_		_					-		
• Relinquished by	(fulsnois)	Un	Dat	1,898	B Received by (signature)	\/	1		\			2/	12	198	1	Total Number of Containers
Company Relinquished by	(signature)	ew Jel	Tim	1:05 pm	Company • Received by L	aboratory (sign	ature)	<u> JE</u>	7				O . Date	30	pan	Addin	tional Comments
Cempany	 		Tin	ue	Company							\	Time				

BOE-C6-0070420



2852 Aiton Ave., Irvine, CA 92606 1014 E. Cooley Dr., Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1843 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(949) 261-1022 FAX (949) 261-1228 (909) 370-4667 FAX (909) 370-1046 (619) 505-9596 FAX (619) 505-9689 (602) 968-8272 FAX (602) 968-1338

Jones Env. Testing Laboratories Client Project ID: B-2263 Sampled: Dec 18, 1998 P.O. Box 5387 T&T, Boeing Received: Dec 23, 1998 Sample Descript: Soil Fullerton, CA 92838 Extracted: Dec 30, 1998 Attention: Joanna Johnson First Sample #: HL03365 Analyzed: Dec 30, 1998 QC Batch: HL30ME3S Reported: Dec 30, 1998

LEAD (EPA 6010B)

Laboratory Number	Sample Description	Reporting Limit mg/Kg (ppm)	Sample Result mg/Kg (ppm)
HL03365	SP-1-3-98	2.0	3.6
HL03366	TK1A-3-98	2.0	4.2
HL03367	TK1B-3-98	2.0	5.1

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Jim Hatreld Project Manager

> Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HL03365.JEL <1 of 2>



2852 Alton Ave., Irvine, CA 92606 1014 E. Cooley Dr., Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(949) 261-1022 FAX (949) 261-1228 (909) 370-4667 FAX (909) 370-1046 (818) 779-1844 FAX (818) 779-1843 (619) 505-9596 FAX (619) 505-9689 (602) 968-8272 FAX (602) 968-1338

Jones Env. Testing Laboratories

P.O. Box 5387 Fullerton, CA 92838

Method Blank

Extracted: Dec 30, 1998 Analyzed: Dec 30, 1998 Reported: Dec 30, 1998

Attention: Joanna Johnson

QC Batch:

HL30ME3S

LEAD (EPA 6010B)

Laboratory		Sample
Description	Reporting Limit mg/Kg (ppm)	Result mg/Kg (ppm)
Method Blank	2.0	N.D.

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Jim Hatfield Project Manager

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HL03365.JEL <2 of 2>



1014 E. Cooley Dr., Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(909) 370-4667 FAX (909) 370-1046 (818) 779-1844 FAX (818) 779-1843 (619) 505-9596 FAX (619) 505-9689 (602) 968-8272 FAX (602) 968-1338

MS/MSD DATA REPORT

METHOD: METALS
Instrument: ICP
Matrix: Soil

Date

Analyzed:

12/30/98

Sample:

HL03650

Batch:

HL30ME3S

Analyte

...

R1

mg/Kg

MS

MSD PR1

PR2

%

RPD

Acceptance Limits

mg/Kg

Sp

mg/Kg mg/Kg

%

%

%

RPD

MEAN

PR

MPR

Lead

0 | 2.0 | 1.80 | 1.82 | 90% | 91% | 1.1% | 91% | 20 | 80-120

Definition of Terms:

R1..... Result of Sample Analysis

Sp. Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1..... Percent Recovery of MS; ((MS-R1) / SP) X 100
PR2.... Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD...... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits..... Statistically determined on an annual basis.

DEL MAR ANALYTICAL

FULLERTON, CA 92635
Tel: 714 449-9937
Fav: 714 449-9685

Chain-Of-Custody Record JONES ENVIRONMENTAL TESTING LABORATORIES Cilent Analysis Requested **Project Name Project Address** Turn Around Requested: Immediate Attention Lab Use Only Rush 24-48 Hours Sample Condition as Received: | Marci Torrance Rush 72-96 Hours Normal **Project Contact** luanna Jehnson Mobile Lab Sealed □yes □ no Laboratory Sample ID Sample Number Sample Location Date Time Container/Comments 12/18/98 TK/B-3-98 O Relinquished by Adapature **Total Number of Containers** Company Time Additional Comments 2:05A @ Relinquished by (slankure) O Received by Laboratory Isignature Date Company DECMAN 6100 PM

BOE-C6-0070424

Appendix B

Marine Chemist Certificate

Thomas D. Beck & Assoc., Inc. dba HARBOR TESTING LABORATORY 24 HOUR PHONE: (562) 492-9646

MARINE CHEMIST CERTIFICATE Serial # 119588

24 HOUR PHONE: (562) 492-9646		
LOTEZ BNGRG	BOEING	18 PEC 98
Survey Requested By UNITED LOUND TANK	Vessel Owner or Agent	199015. NORMANNE Date
Vessel 6 KOLINE	Type of Vessel LEL, O2, V(JUM)	Specific Location of Vessel
Last Cargo	Tests Performed	Time Survey Completed
UNDERBRUWN STORME TANK MARKED WITH XELLOW SPRAY PAINT	SAFE FOR	HOT WORKERS
MSA M (ROGARD SIN	3236 AMIDRATED	044-12 (18DE 98

In the event of any physical or atmospheric adversely affecting the STANDARD SAFETY DESIGNATIONS assigned to any of the above spaces, or if any doubt, immediately stop all work and contact the undersigned Marine Chemist.

QUALIFICATIONS: Transfer of ballast of manipulation of valves or closure equipment tending to alter conditions in pipe lines, tanks or compartments subject to gas accumulation, unless specifically approved in this Certificate, requires inspection and endorsement or reissue of Certificate for the spaces so affected. All lines, vents, heating coils, valves, and similarly enclosed appurtenances shall be considered "not safe" unless otherwise specifically designated.

STANDARD SAFETY DESIGNATIONS (partial list, paraphrased from NFPA 306 Subsections 2-3.1 through 2-3.5, and Subsection 6-3.2)

SAFE FOR WORKERS: Means that in the compartment of space so designated: (a) the oxygen content of the atmosphere is at least 19.5 percent by volume; and that, (b) toxic materials in the atmosphere are within permissible concentrations; and that, (c) the residues are not capable of producing toxic materials under existing atmospheric conditions while maintained as directed on the Marine Chemist's Certificate.

NOT SAFE FOR WORKERS: Means that in the compartment of space so designated, the requirements of Safe for Workers have not been met.

ENTER WITH RESTRICTIONS: Means that in any compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are specified.

SAFE FOR HOT WORK: Means that in any compartment designated: (a) oxygen content of the atmosphere is at least 19.5 percent by volume, with the exception of inerted spaces or where external hot work is to be performed; and that, (b) the concentration of flammable materials in the atmosphere is below 10 percent of the lower flammable limit; and that, (c) the residues are not capable of producing a higher concentration than permitted by (b) above under existing atmospheric conditions in the presence of fire, and while maintained as directed on the Marine Chemist's Certificate; and further, that, (d) all adjacent spaces containing or having contained flammable or combustible materials have been cleaned sufficiently to prevent the spread of fire, or are satisfactorily inerted, or, in the case of fuel tanks or lube oil tanks, or engine room or fire room bilges, have been treated in accordance with the Marine Chemist's requirements.

NOT SAFE FOR HOT WORK: Means that in the compartment so designated, the requirements of Safe for Hot Work have not been met.

CHEMIST'S ENDORSEMENT. This is to certify that I have personally determined that all spaces in the foregoing list are in accordance with NFPA 306 Control of Gas Hazards on Vessels and have found the condition of each to be in accordance with its assigned designation.

"The undersigned acknowledges receipt of this Certificate under Section 2-6 of NFPA 306 and understands conditions and limitations under which it was issued."

This Certificate is based on conditions existing at the time the inspection herein set forth was completed and size of subject to compliance with all qualifications and instructions.

______ Si

Marine Chemist TOW DC

Certicate No.

Appendix C

Soil-Compaction Report

SEE APPRIDIX H

Appendix D

Uniform Hazardous Waste Manifest

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID N		Manifest Documen	i No.	2. Page 1	Information in the sl is not required by Fo	
3. Generator's Name and Mailing Address UGUGIAS ARCTAIL CO., 17/15 UD119-121		1 - 1 - 1 - 1 - 1 - 1	3 3 3	A. State	Manifest Document N	lumber 983 (09515
1855 Lakewood Blvd Long Send				B. Stote (Generator's ID		
4. Generator's Phone (362)85.3524				1800 Contract	THE PROPERTY OF THE PROPERTY O	00569	1 R
5. Transporter 1 Company Name	6. US E	PA ID Number		C. State	Fransporter's ID		
Ecology Control industries	ÇıÄı	ପ୍ରଥମଣ୍ଡ	3 0 1 7 3	D. Transp	oorter's Phone	(310) 320	j. 2555
7. Transporter 2 Company Name		PA ID Number		E. State 1	ransporter's ID	776665576	,
		1111	1111	Service and	orter's Phone		
Designated Facility Name and Site Address Geffence Kerdoop	10. US E	PA ID Number	<u> </u>	113	Facility's ID	24200	PARTITE
2000 North Alameda Cuser							
Compron. CA :0222	C AT	Tiolololol	10050	H. Facilit	y's Phone	(310) 537	7-7100
11. US DOT Description (including Proper Shippin			12. Cor	tainers	13. Total	14. Unit	
	· · · · · · · · · · · · · · · · · · ·		No.	Туре	Quantity	Wt/Vol L Was	te Number
a. Waste Planneshie Accurs 160	a manageleti (i (iMi)	993 Hall (F00	1)		04520	Sidle	331
			001		10890	P EPA/O	ther D00 1
b.				 	101319	State	
1						EPA/O	
\ 	· ·			<u> </u>			
「 [、]						State	
0 R			1 1		1	EPA/O	ther
d.	· · · · · · · · · · · · · · · · · · ·			 	 	State	Control of the Contro
						Sidle	
			111	1	1111	EPA/O	ther
J. Additional Descriptions for Materials Listed About 150524 Motors and About				K: Handl	ing Codes for Waste	s Listed Above	
11a. 159524. Water contaminated with g				G.		b. 📜 📜	
					THE WAR TO THE TANK OF THE TAN	A CHARLES	
				5 444			
15. Special Handling Instructions and Additional 24 Hour Emergency releptions Number	Information	hamteen DOT	EP/3#1101 19	<u> </u>	real and the second		
Site Address 19503 South Normandi	e Ave Torrance CA L	:0502	CNO# (Id / 12)	Þ			
16. GENERATOR'S CERTIFICATION: I hereby dec marked, and labeled, and are in all respects	lare that the contents of this co in proper condition for transp	nsignment are fully at ort by highway accor	nd accurately descri ding to applicable i	bed above internations	by proper shipping n al and national gover	ame and are classifie rnment regulations.	d, packed,
If I am a large quantity generator, I certify the practicable and that I have selected the practicable and	icable method at treatment st	orage, or disposal cu	irrently available to	me which	minimizes the preser	at and future threat to	n human health
and the environment; OR, if I am a small qui available to me and that I can afford.	antity generator, I have made	a good taith ettort to	o minimize my wast	te generatio	on and select the bes	t waste management	method that is
Printed/Typed Name	Sig	nature 7		//	4	Month	Day Year
1 Line and -attend	<u></u>	11116	<u>(3) 40</u>	119	1.7	11 10/11	11-11-
17. Transporter 1 Acknowledgement of Receipt of Printed/Typed Name		nature	<u> </u>	/-		Month	Day Year
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	l sig	······································		<i>e</i>			7719
18. Transporter 2 Acknowledgement of Receipt of Printed/Typed Name							
Frinted/Typed Name	Sig	nature				Month	Day Year
19. Discrepancy Indication Space							1 1 1
A]							
20. Facility Owner or Operator Certification of re	ceipt of hazardous materials	overed by this manifo	st except as noted :	n item 10	· · · · · · · · · · · · · · · · · · ·		
Printed/Typed Name		nature	2. Ovcebi da Holed I	. nem 17.	,, .,	Month	Day Year

DO NOT WRITE BELOW THIS LINE.

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802: WITHIN CALIFORNIA, CALL 1-800-852-7550

Appendix E

Tank degassing Certificate



WESTERN

ENVIRONMENTAL

ENGINEERS

CO.

1780 E. McFadden Ave. (Suite 117) Santa Ana, CA 92705 (714) 542-2644 FAX (714) 542-2520

January 26, 1999

To: Boeing Co.

Lopez General Engineering Contractors Inc.

To Whom It May Concern:

We would like to inform you that WEECO has performed the degassing services to the following addresses on specified dates.

On December 15, 1998 at 3558 Lakewood Boulevard, Long Beach, California. AQMD notification reference number was DL 98-0347.

On December 17, 1998 at 19501 Normandie Avenue, Torrance, California. AQMD notification reference number was DL 98-0435.

If you have any questions, please contact Charles Choi at 714) 542-2644.

Sincerely,

Charles Choi

Western Environmental Engineers Co.

Appendix F

Tank Destruction Certificate



December 21, 1998

TRANSMITTED VIA FAX AND U.S. MAIL

Mr. Jorge Berdini BOEING 3855 Lakewood Blvd. Long Beach, CA 90846

SUBJECT: TANK DESTRUCTION CERTIFICATE

Dear Mr. Berdini,

This letter is to certify tank number(s): * 9588

In accordance with Marine Chemist Certificate, 9588 (1) underground storage tank was received from Boeing Aircraft - 19901 S. Normandie Ave., Torrance.

Tank was torch cut into scrap classification of #1 Prepared Scrap, cut into pieces no longer than (5) five feet or wider than 1 1/2 feet in size, therefore rendering this tank into scrap steel and sold as such. Tank was cut at Lopez yard, 222 "F" Street, Wilmington, California.

Burner(s):	Santos Gonzalez	Authorized Signature		
	Javier Vasquez			
Customer Na	me : <u>Boeing Air</u>	raft - Torrance		

Customer P.O.#:

Not Valid without the corporate seal and signature

2633 E. 28th STREET, STE. 624, SIGNAL HILL, CA 90806 TEL (310) 426-1196 FAX (310) 595-8546

Appendix G

Tank Removal Permit

LUS ANGELES CITY FIRE DEPARTMENT Division 5 Permit - Atmospheric Underground Tank Fire Dept Use Only LAFD Unified Program Facility ID: Permit No. Data Managment Unit: Fire Station #: Date Granted: 7572 12/9/98 79 30179-3 **Enforcement Inspector** Permit Type: **Expiration Date:** 12/9/99 Stivason Abandonment by Removal LOCATION INFORMATION Doing Business As (DBA): EPA ID No. (not required for Installation or Monitoring) **BOEING - McDONNELL DOUGLAS** CAC 001487880 Address: Number Dir. Street Name St., Ave., Blvd., etc. Phone No.: 19503 S **NORMANDIE** AVE City: State: Zip: Los Angeles CA PROPERTY OWNER Name: **BOEING - McDONNELL DOUGLAS** Phone No.: 562-497-5849 Address: 4060 N. LAKEWOOD BLVD. 6th FLOOR City: State: LONG BEACH CA 90808-1700 Print Name: Signature: **NEIL HAINES** CONTRACTOR INFORMATION Company Name: Maness Environmental Phone No.: 310-595-4555 Address: PO Box 90939 1101 E. Spring St City: Zip: State: Calif. Long Beach 90809 City Business Number: State Contractors Number: Work Comp Number: 704659 553633 7081738 Print Name: Title: ED WARDLE PROJ. MGR ITEM NOTES: **UST(s)** Installation UST(s) Abandonment by Removal 1 - 12K GASOLINE, 1 DISPENSER 1 UST(s) Abandonment-In-Place UST(s) Tank Entry / Lining / Repair LOS ANGELES FIRE DEPARTMENT UST(s) Add to / Alter: Monitor / Piping / Disp. BUREAU OF FIRE PRE Site Assessment

Inspector Signature:

Emergency Plan Check / Site Assessment

Inspector Name: Nealy



CITY OF LOS ANGELES

INVOICE

Applicant/Contractor Information: Name of Applicant:	nd Storage Tank Fees f	oi Selvice		Invoice No.: Permit No.:	1572 7572	
Name of Applicant: Representing:				Permit No.:	7572	
Representing:			j : 1			
			1	Permit Type:	Abandonment by Removal	
(COMMANY MAINEORII)	Maness Environmental					
• •	310-595-4555		;	Inspection		
Site Information: LAFD Facility ID No.: 001361-1 Business Name (DBA): BOEING - McDONNELL DOUGLAS				District: Plan Check	423	
Business Name (DBA):	BUEING - McDONNELL DOU	JOUGLAS		Inspector:	Nealy Stivason	
Site Address:	19503 S NORMANDIE AVE			Enforcement Inspector:		
	Los Angeles City	CA State	Zip			
Installation			\$306.00		166.	
Installation					Fee:	
Abandonment by Removal	Number of Tanks:	1	\$204.00 plus \$102.00 fo additional tank	r eacn	\$204.00	
Abandonment-in-Place			<i>\$306.00</i>			
Add to/Alter: Monitoring, Pip	ping, Dispenser		\$306.00			
Tank Entry, Lining, Repair			\$306.00			
			\$102.00			
Site Assessment				1	!	
Site Assessment Emergency Plan Check / Site	e Assessment		\$408.00			

Plan Check and Inspection services are calculated on a fee for service basis. Each type of transaction has been assigned a charge based on the estimated time required for the service.

If Plan Check/Inspection services exceed the assigned hours, additional charges will accrue in six minute increments. These additional charges will be billed to the Responsible Party.

For Cash Payments:
BILLING & ACCOUNTS RECEIVABLE
10TH FLOOR, RM. NO. 1070

PAID
12-9-9B.

AMOUNT PAID \$

SIGNATURE:

SIGNATURE:

SIGNATURE:



Grading

City of Los Angeles - Department of Building and Safety

APPLICATION FOR GRADING PERMIT

Over the Counter Permit

AND GRADING CERTIFICATE

Status:

Ready to Issue

Status Date: 12/14/98

Printed on: 12/14/98

15:02:01

I. TRACT RANCHO SAN PEDRO LOT(s)

BLOCK

ARB

MAP REF#

PARCEL ID # (PIN) 3 2. BOOK/PAGE/PARCEL

MARIA DE LOS REYES DOMIN

SCC 3284 CF 145 MA 057B193

7351 - 003 - 014

3. PARCEL INFORMATION

BAS Branch Office - SP

Council District - 15 Census Tract - 2920.000 District Map - 057B193

Energy Zone - 6 Lot Size - IRR Lot Type - Corner

Thomas Brothers Map Grid - 763

Thomas Brothers Map Grid - 764

ZONE(S): M3-1 /

4. DOCUMENTS

5. CHECKLIST ITEMS

6. PROPERTY OWNER, TENANT, APPLICANT INFORMATION

Mcdonnell Douglas Realty Co

4060 Lakewood Blvd 6 FLR

LONG BEACH CA 90808

Tenant:

Applicant: (Relationship: Contractor)

(562) 426-1196

7.EXISTING USE

PROPOSED USE

60 Grading - Non-Hillside

8. DESCRIPTION OF WORK

REMOVE ONE 12,000 GAS UNDERGROUND FUEL TANK (GASOLINE)

& BACK FILL(9'x35'x12'deep)

9. # Bldgs on Site & Use: MANUF

10. APPLICATION PROCESSING INFORMATION

BLDG. PC By:

DAS PC By:

OK for Cashier: Pete Ortiz

Coord. OK:

Signature:

Date:

11. PROJECT VALUATION & FEE INFORMATION Final Fee Period

PC Valuation: Permit Valuation: 140 cu yd FINAL TOTAL Grading 354.65 Permit Fee Subtotal Grading 295.00

Plan Check Subtotal Grading O.S. Surcharge

Sys. Surcharge Planning Surcharge Planning Surcharge Misc Fee Permit Issuing Fee

6.30 18.90

9.45 5.00

20.00

Sewer Cap ID:

Total Bond(s) Due:

12. ATTACHMENTS

Plot Plan

For information and/or inspection requests originating within LA County, call toil-free (888)-LA4BUILD; outside LA County, call (213)-977-6941.

For Cashier's Use Only

W/0 #: 83002726


12/14/98 03:21:20PH SP01 T-2818 C 13

GRADING PERMIT 295.00 INVOICE \$ 0000000 PF

SYS DEV THE STOP CITY PLAN SERC

TOTAL CHECK

985P 29234



there it by 12-10-98

48129.21 to be builting

RECEIVED

ROM

62

7310

N

99

õ

-

C

C

529421-36

LOS ANGELES COUNTY TAX COLLECTOR P.O. BOX 5408B LOS ANGBLES, CA 90054-0088

73805

DUE FEB. 1. 1000 DELINQUENT APR. 10, 1999 MAKE CHECKS PAYABLE TO: _____

USE THEIR HUMBERS OF AR CIRCAL AND TORRESPONDENCE Year Son, No Map Book Page Parce INDICATE AMOUNT PA 316263 26

19

THUUMA

582149 5

844:7

17558 2

5181:1

14407 6

69886!5

18545 52

2779!70

4433113

6593 OA

55715:44

18614;52 11:88

481292 15

316263 26

797555 41

43886

B34 13

Herpedts 04-10-99 add pendly and con

31636.32 to 2 will be .. Tread

347899~58

LOS ANGELES COUNTY TAX COLLECTOR P.O. BOX 54088 LOS ANGELES, CA 90054-0088

98794000373510030140044129215005294213680511210

99498000373510030140031626326003478995888620412

Appendix H

Soil Compaction Report

NorCal Engineering

Soils and Geotechnical Consultants 10641 Humbolt Street Los Alamitos, CA 90720 (562) 799-9469 Fax (562) 799-9459

January 26, 1999

Project Number 7819-99

Lopez Construction 2633 E. 28th Street, No. 624 Signal Hill, California 90806

RE: Observation and Testing of Excavation Backfill Operations - Boeing

Facility - Located at 19907 South Normandie Avenue, in the City of Los

Angeles, California

Dear Sirs:

Pursuant to your request, this firm has observed and tested excavation backfill operations at the above referenced project. Results of the compaction tests are attached and locations of these tests are shown on the accompanying Site Plan. All work was in accordance with all present day standards of the Geotechnical Engineering Industry.

Backfill Operations

The fill area consisted of an excavation approximately 20 feet by 35 feet with a maximum depth of 10 feet below ground surface. The excavation was removed of all demolition debris and low density soils to expose competent native soils. The excavation bottom was observed and approved by this firm prior to placement of fill. The tank excavation was backfilled with pea gravel to within one foot below ground surface and compacted and capped with on-site soils to final grade.

Fill soils placed were compacted to a minimum of 90% of the laboratory standard in lifts not in excess of eight inches in thickness. A backhoe with sheepsfoot wheel was utilized for compaction control. No additional water was necessary to provided moisture control. The approximate limits of compacted fill are indicated on the attached Site Plan.

Laboratory/Field Testing

The relative compaction was determined by Sand Cone Method (ASTM: D1556-82) and by the Drive Tube Method (ASTM: D2937). The maximum density of the fill soils was obtained by the laboratory standard (ASTM: D1557-78) and results are shown on Table I. Tests were performed a minimum of every 500 cubic yards placed and every two feet in depth of fill placed. Results of field density tests are presented in Table II. No chemical analysis was performed by NorCal Engineering on the tank excavation nor the backfill soils.

Conclusions

The geotechnical engineering aspects of the backfill operations have been observed and are in compliance with the geotechnical engineer's recommendations. The backfill meets secondary fill requirements for support of pavement and floor slab. The excavation has been backfilled to the approval of this firm and is suitable for its intended use.

We appreciate this opportunity to be of service to you. If you have any further questions, please do not hesitate to contact the undersigned.

Respectfully submitted, NORCAL ENGINEERING

Keith D. Tucker Project Engineer

R.G.E. 841

No. 841 Exp. 12/31/00

Scott D. Spensiero Project Manager

TABLE I MAXIMUM DENSITY TESTS (ASTM: D1557-78)

Sample	Classification	Optimum <u>Moisture</u>	Maximum Dry Density (lbs./cu.ft.)	
	SAND fine to medium grained, slightly clayey occasional gravel	11.0	124.0	

TABLE II COMPACTION TEST RESULTS

Date of <u>Test</u>	Test <u>No.</u>	*Depth	Percent <u>Moisture</u>	Unit Wt. lbs./cu.ft.	Relative Compaction	Soil Type
12/18/98	101	10.0-10.5	11.5	117.4	95	1
1/4/99	102	0.0-0.5	10.0	115.4	93	i

*Depth below finish grade (in feet)

NorCal Engineering

^{**}Retest of failing tests after area reworked

